


FIG. 1



09832116-041101

FIG. 2





FIG. 3



09832116-041101

FIG. 4




FIG. 5A




FIG. 5B




FIG. 5C





FIG. 6

101140' 91128860

FIG. 7

2000P ACCUMULATIVE ERROR




FIG. 8




FIG. 9




FIG. 10








FIG. 11



12/46

FIG. 12



09832116.041101

FIG. 13




FIG. 14




FIG. 15A




FIG. 15B




FIG. 16A




FIG. 16B




FIG. 17B




FIG. 18A




FIG. 18B




FIG. 19A




FIG. 19B





FIG. 20



09832116-041101

FIG. 21




FIG. 22




FIG. 23




FIG. 24




FIG. 25





FIG. 26



27/46

FIG. 27A




FIG. 27B





FIG. 27C



09832116-041101

FIG. 28




FIG. 29A




FIG. 29B




FIG. 29C




FIG. 29D




FIG. 30A




FIG. 30B




FIG. 31A




FIG. 31B




FIG. 31C




FIG. 32A




FIG. 32B




FIG. 32C





FIG. 33

MRA ROTARY SCALE 103



DETECTION HEAD

TOPPNO 9112E860

FIG. 34




FIG. 35




FIG. 36




FIG. 37





FIG. 38



09832116-041101

FIG. 39




FIG. 40





FIG. 41



09832116-041101

FIG. 42




FIG. 43





FIG. 44



09832116.041101

FIG. 45




FIG. 46

